

Percussion Maintenance

Supplies Needed: Soft cloth, glass cleaner, cotton swab.

Daily

1. Inspect drum and stand for loose lugs or screws
2. Inspect drum head for slits or holes
3. Inspect bells for loose screws

Weekly

1. Wipe off drum head and shell with a clean cloth
2. Wipe off bells and stand with a clean cloth

Monthly

1. Clean Drum with a clean cloth and glass cleaner
2. Clean bells with a clean cloth and glass cleaner
3. Clean and vacuum case